

COLLISION REPAIR INFORMATION


FOR THE TOYOTA DEALER

TITLE: AVAILABILITY OF A REINFORCEMENT PLATE BETWEEN THE INNER FRONT FENDER APRON AND THE OUTER LOWER DASH PANEL PAGE 1 of 1

SECTION: STRUCTURAL REPAIR BULLETIN #13
MODELS: RN SERIES
DATE: AUGUST 1986



As part of Toyota's continuing effort to provide collision repair shops with efficient, cost saving repairs, Toyota Motor Corporation has recently announced the availability of a replacement reinforcement plate (previously not available through Toyota Parts) that connects the inner front fender apron to the outer lower dash panel. This part is a direct replacement part for the original equipment part that is attached to the body during factory assembly (see photo below).



Part Numbers:

All models up to and including 1983	RH 55133-89101 LH 55134-89101
All models up to and including 1984	RH 55133-89103 LH 55134-89103

NOTE: PLEASE ROUTE THIS BULLETIN TO THE BODY SHOP MANAGER OR THE PERSON RESPONSIBLE FOR COLLISION REPAIR INFORMATION .