

# COLLISION REPAIR INFORMATION

## FOR THE TOYOTA DEALER

TITLE: SRS & HV WIRING REPAIRS

SECTION: ELECTRICAL BULLETIN # 156

MODELS: ALL TOYOTA, LEXUS, and SCION MODELS

DATE: AUGUST 2007

---

**There are no approved repairs to Supplemental Restraint System (SRS) or High Voltage (HV) wiring or connectors.** SRS system wiring and connectors are color coded yellow, and HV wiring is orange, however, vehicle-specific wiring diagrams are the best source for identifying wiring in these circuits. Wiring diagrams are available through the Technical Information System (TIS) at [www.techinfo.toyota.com](http://www.techinfo.toyota.com).

If SRS or HV wiring or connectors are suspected of damage they should be inspected thoroughly. Damaged wiring and/or connectors require replacement of the affected harness. Follow all precautions and procedures outlined in model-specific repair manuals for replacing SRS wiring or components. **Only Certified Hybrid Service Technicians are qualified to replace HV system wiring and components.**



**Example SRS Wiring  
(yellow)**



**Example HV Wiring  
(orange)**

**PLEASE ROUTE THIS BULLETIN TO YOUR COLLISION REPAIR CENTER  
MANAGER AND COLLISION REPAIR TECHNICIANS**