

# COLLISION REPAIR INFORMATION

## FOR THE COLLISION REPAIR PROFESSIONAL


TITLE: QUARTER PANEL SERVICE PART MODIFICATION

SECTION: EXTERIOR BULLETIN #162

MODELS: TOYOTA & LEXUS AS LISTED

DATE: FEBRUARY 2008

To improve storage and distribution logistics and reduce waste material, a change to Quarter Panel service part cuts have been made on select models. Implementation timing will vary due to number of in-stock units. Superseding part numbers will be issued as new stock arrives. The revised panel cuts are 50 mm in the roof direction from the specified cut-and-join location listed in Collision Damage Repair Manuals available from the Technical Information System (TIS) at ([www.techinfo.toyota.com](http://www.techinfo.toyota.com)). This revision does not represent any change to replacement specifications. Please refer to the illustrations and model-specific references below.



Model Name	Model Code	Production Date
LS430	UCF30	08/2000-
LS400	UCF20	10/1994-08/2000
GS300	JZS147	01/1993-08/1997
GS430/300	UZS16, JZS160	08/1997-
ES300	MCV3	07/2001-
IS300/250	GXE10, JCE10	05/2000-
Prius	NHW20	08/2003-

PLEASE ROUTE THIS BULLETIN TO YOUR COLLISION REPAIR CENTER MANAGER AND COLLISION REPAIR TECHNICIANS

