

# COLLISION REPAIR INFORMATION

## FOR THE TOYOTA DEALER

TITLE: REPLACEMENT CERTIFICATION LABELS

PAGE 1 of 1

SECTION: GENERAL INFORMATION BULLETIN #88

MODELS: ALL TOYOTA/LEXUS MODELS

DATE: DECEMBER 1998



Replacement regulation certification labels (vinyl label affixed to driver's door or "B" pillar) **may be** available from Toyota for vehicles involved in a collision where the label was damaged or is attached to a part will be replaced during a repair.



MFD. BY: TOYOTA MOTOR MANUFACTURING  
CANADA INC. (59/93)  
CWR 3415L8 GAWR FR 1770LB RR 1690LB  
THIS VEHICLE CONFORMS TO ALL APPLICABLE  
FEDERAL MOTOR VEHICLE SAFETY STANDARDS AND  
THEFT PREVENTION STANDARDS IN EFFECT ON  
THE DATE OF MANUFACTURE SHOWN ABOVE  
271AED1AENG123456 PASS CAR  
C/TR: 180/J014 MODEL: AESSL-DEHKA  
A/TR: -552/A131L MADE IN CANADA  
AACC491701

Certification Label

Application and information for ordering the label can be obtained to Toyota Technical Service Bulletin (TSB PG004-97) or Lexus Technical Service Information Bulletin (TSIB PG003-097), which is available through your respective dealership Service or Parts Manager.

**NOTE:** Processing a new label will be delayed if the old certification label is not available. A new label may not be available if your vehicle is more than five years old and/or the old label is not attached to the application.

All replacement labels for damaged vehicles are subject to approval by the Toyota Technical Compliance Department.

**NOTE: PLEASE ROUTE THIS BULLETIN TO YOUR COLLISION REPAIR CENTER MANAGER**