


COLLISION REPAIR INFORMATION

FOR THE COLLISION REPAIR PROFESSIONAL

TITLE: CAMRY BUMPER DISCOLORATION
SECTION: REFINISH BULLETIN #171
MODELS: CAMRY AS LISTED
DATE: FEBRUARY 2009

The listed Camry OE service parts may exhibit a color difference in the form of visible marking of the exterior surface similar to the bumper in the photo provided below. While the markings are visible from the outer surface, there have been no issues effecting refinish operations, paint adhesion, or bleed-through reported or discovered during refinish validation tests. Toyota strongly recommends following preparation and refinishing procedures outlined in Collision Repair Information Bulletin (CRIB) #170.

Part Number	Model Code	Model Application	Prod. Beg. Date	Prod. End Date
52119-06900	787H	Camry (NAP)	1991	1992
52159-06900	787H	Camry (NAP)	1991	1992
52159-06901	787H	Camry (NAP)	1992	1994
52159-AA900	063W	Camry (NAP)	1997	1999
52159-AA902	138W	Camry (NAP)	1999	2001
52119-AA900	034W	Camry (NAP)	1996	1996



**PLEASE ROUTE THIS BULLETIN TO YOUR COLLISION REPAIR CENTER
MANAGER AND COLLISION REPAIR TECHNICIANS**

