

COLLISION REPAIR INFORMATION


FOR THE COLLISION REPAIR PROFESSIONAL

TITLE: REPLACEMENT CERTIFICATION LABELS AND VIN PLATES
SECTION: EXTERIOR BULLETIN #164
MODELS: ALL TOYOTA, LEXUS, and SCION
DATE: SEPTEMBER 2008

Replacement Certification Labels and on a limited basis Vehicle Identification Number (VIN) plates are available by application. If these identifiers require replacement or transfer to a replacement component, follow instructions outlined in these Technical Service Bulletins:

- T-SB-0144-08 Replacement Certification Labels - Toyota
- L-SB-0048-08 Replacement Certification Labels - Lexus
- S-SB-0039-08 Replacement Certification Labels - Scion
- PG007-07 Replacement VIN Plates - Toyota
- PG007-07 Replacement VIN Plates - Lexus
- PG009-07 Replacement VIN Plates - Scion

Service Bulletins are available from the Technical Information System (TIS) at www.techinfo.toyota.com.



**PLEASE ROUTE THIS BULLETIN TO YOUR COLLISION REPAIR CENTER
MANAGER AND COLLISION REPAIR TECHNICIANS**

